

Instructions for Use for

Absorbance Reader

INFINITE F50 PLUS

and Software

MAGELLAN



Document Part No.: 30186912

2022-01

Document Revision No.: 1.1

Firmware Version: 3.33

Software Version Magellan: 7.5







WARNING

CAREFULLY READ AND FOLLOW THE INSTRUCTIONS FOR USE BEFORE OPERATING THE INSTRUMENT.

Notice

Every effort has been made to avoid errors in text and diagrams; however, Tecan Austria GmbH assumes no responsibility for any errors, which may appear in this document.

It is the policy of Tecan Austria GmbH to improve products as new techniques and components become available. Therefore, Tecan Austria GmbH reserves the right to change specifications at any time *with appropriate verification, validation, and approvals.*

We would appreciate any comments on this document.



Manufacturer

Tecan Austria GmbH Untersbergstr. 1A A-5082 Grödig, Austria

T: +43 6246 89330 F: +43 6246 72 770

www.tecan.com

E-mail: office.austria@tecan.com

Copyright Information

The contents of this document are the property of Tecan Austria GmbH and are not to be copied, reproduced, or transferred to another person or persons without prior written permission.

Copyright © Tecan Austria GmbH All rights reserved. Printed in Austria.

Declaration for EU Certificate

See the last page of these Instructions for Use.

About the Instructions for Use

Original instructions. This document is intended as **Instructions for Use** (IFU) for the INFINITE F50 PLUS absorbance reader, which is designed to measure the light absorbance (optical density) of samples in 96-well microplates. It is intended as reference and instruction for the user.

This document instructs how to:

- Install the instrument
- Operate the instrument
- Clean and maintain the instrument

Remarks on Screenshots

The version number displayed in screenshots may not always be the one of the currently released version. Screenshots are replaced only if the content related to application has changed.



Warnings, Cautions, and Notes

The following types of notices are used throughout this publication to highlight important information or to warn the user of potentially dangerous situations:



Note Gives helpful information.



CAUTION INDICATES A POSSIBILITY OF INSTRUMENT DAMAGE OR DATA LOSS IF INSTRUCTIONS ARE NOT FOLLOWED.



WARNING

INDICATES THE POSSIBILITY OF SEVERE PERSONAL INJURY, LOSS OF LIFE OR EQUIPMENT DAMAGE IF THE INSTRUCTIONS ARE NOT FOLLOWED.



WARNING

INDICATES THE POSSIBLE PRESENCE OF BIOLOGICALLY HAZARDOUS MATERIAL. PROPER LABORATORY SAFETY PRECAUTIONS MUST BE OBSERVED.



WARNING

THIS SYMBOL INDICATES THE POSSIBLE PRESENCE OF FLAMMABLE MATERIALS AND A RISK OF FIRE. PROPER LABORATORY SAFETY PRECAUTIONS MUST BE OBSERVED.



ATTENTION

DIRECTIVE 2012/19/EU ON WASTE ELECTRICAL AND ELECTRONIC EQUIPMENT (WEEE)

NEGATIVE ENVIRONMENTAL IMPACTS ASSOCIATED WITH THE TREATMENT OF WASTE.

- DO NOT TREAT ELECTRICAL AND ELECTRONIC EQUIPMENT AS UNSORTED MUNICIPAL WASTE.
- COLLECT WASTE FROM ELECTRICAL AND ELECTRONIC EQUIPMENT SEPARATELY.



Table of Contents

1.	Safe	Safety7				
	1.1	Instrur	ment Safety	7		
2.	Gen	eral		9		
	2.1	Intend	led Use	9		
	2.2	Princip	ple of Operation	10		
	2.3	User P	Profile	11		
		2.3.1	Professional User - Administrator Level	11		
		2.3.2	End User or Routine User	11		
		2.3.3	Service Technician	11		
3.	Gett	ing Star	rted	13		
	3.1	_	cking and Inspection			
		3.1.1	Inspection of Delivered Packaging			
		3.1.2	Unpacking Procedure	13		
	3.2	Power	Requirements	14		
	3.3	Enviro	onmental Requirements	14		
	3.4	Systen	m Requirements	15		
	3.5	Switch	hing ON the Instrument	16		
	3.6	Softwa	are			
		3.6.1	Introduction / Intended Use			
		3.6.2	Installation Procedure	17		
		3.6.3	Installation Qualification			
		3.6.4	Start Working with Magellan			
	3.7	_	lan - Measurement Parameter Editor			
		3.7.1	Control Bar			
		3.7.2	Workflow Pane			
		3.7.3	Info Pane			
	3.8	_	lan - Defining Measurements			
		3.8.1	Defining Endpoint Measurements			
		3.8.2	Defining Multilabel Measurements			
		3.8.3	Defining Kinetic Measurements			
	2.0	3.8.4	Indenting and Releasing Program Elementsizing for Best Performance			
	3.9	3.9.1	Instrument Location			
		3.9.1	Operating Procedure			
	l 4.		Features			
4.						
	4.1	Instrur	ment Features			
	4.0	4.1.1	Microplate Shaking			
	4.2 4.3		ment Description			
	4.3 4.4		ment Specifications			
	4.4	4.4.1	General Specifications			
		4.4.2	Measurement Specifications			
		4.4.3	Microplates			
	4.5		ment Accessories			
5.	Qua		ntrol			
٠.	5.1	•	uction			
	5.2		heck Procedure			
	5.3		tional Qualification (OQ)			
	3.0	5.3.1	MultiCheck Test			
		5.3.2	Microplate Test			
		5.3.3	Instrument Precision with Liquid Samples			
		5.3.4	Instrument Linearity with Liquid Samples			
6.	Δnn		Example			
٥.	6.1		uction			
	6.2		by-Step Example: Quantitative ELISA			
	0.2	orch-n	J Stop Example: qualitative ELIOA			



		6.2.1	Test Kit Description	41
		6.2.2	Create a Method	
		6.2.3	Organize Printed Report	53
		6.2.4	Run the Method	57
		6.2.5	Evaluate the Result	58
		6.2.6	Summary of Definition of Quantitative ELISA in Magellan	60
7.	Clea	ning, Ma	aintenance, and Disposal	63
	7.1	Introdu	uction	63
	7.2	Cleanir	ng the Instrument	63
	7.3	Instrun	nent Disinfection	64
		7.3.1	Disinfection Solutions	64
		7.3.2	Disinfection Procedure	65
		7.3.3	Safety Certificate	
	7.4	Preven	tive Maintenance Plan for INFINITE F50 PLUS	67
		7.4.1	Monthly	
		7.4.2	Every 4 Years	
	7.5		Replacement and Installation	
		7.5.1	Filter Switching Procedure	
		7.5.2	Defining Filters	
	7.6	Dispos	sal	71
		7.6.1	Introduction	
		7.6.2	Disposal of Packing Material	
		7.6.3	Disposal of Operating Material	
		7.6.4	Disposal of the Instrument	72
8.	Trou	ıbleshoo	oting	73
	8.1	Introdu	uction	73
		8.1.1	Table of Error Messages and Troubleshooting	
		8.1.2	Definition of 'Overflow'	74
		8.1.3	Power Failure	74
9.	Abb	reviatior	ns, Trademarks, and Symbols	75
	9.1	Abbrev	viations	75
	9.2	Traden	narks	76
	9.3	Symbo	ols	77
Inde	x			79
Tac	an Cui	stomar S	Sunnort	21



1. Safety

1.1 Instrument Safety

- 1. Always follow basic safety precautions when using this product to reduce the risk of injury, fire, or electrical shock.
- Read and understand all information in the Instructions for Use (IFU).
 Failure to read, understand, and follow the instructions in this document may result in damage to the product, injury to operating personnel, or poor instrument performance. Tecan is not responsible for damage or injuries resulting from incorrect handling of the device.
- 3. Observe all WARNING and CAUTION statements in this document.
- 4. Always disconnect the device from the main power supply prior to cleaning and disinfection.
- 5. Never open the instrument's housing.
- Observe proper laboratory safety precautions such as wearing protective clothing (e.g. gloves, lab coat, and safety glasses) and the application of approved laboratory safety procedures.



CAUTION

IF THE INSTRUCTIONS GIVEN IN THIS PUBLICATION ARE NOT CORRECTLY FOLLOWED, THE INSTRUMENT MAY BECOME DAMAGED OR PROCEDURES MAY NOT BE CORRECTLY PERFORMED AND THE SAFETY OF THE INSTRUMENT CANNOT BE GUARANTEED.

It is assumed that the instrument operators, because of their vocational experience, are familiar with the necessary safety precautions for handling chemicals and bio-hazardous substances.

Adhere to the following laws and guidelines:

- National industrial protection law
- Accident prevention regulations
- Safety data sheets of the reagent manufacturers

WARNING

DEPENDING ON THE APPLICATIONS, PARTS OF THE INFINITE F50 PLUS MAY COME IN CONTACT WITH BIOHAZARDOUS/INFECTIOUS MATERIAL.

MAKE SURE THAT ONLY QUALIFIED PERSONNEL OPERATE THE INSTRUMENT. IN CASE OF SERVICE OR WHEN RELOCATING OR DISPOSING OF THE INSTRUMENT, ALWAYS DISINFECT THE INSTRUMENT ACCORDING TO THE INSTRUCTIONS GIVEN IN THIS DOCUMENT.

OBSERVE PROPER LABORATORY SAFETY PRECAUTIONS SUCH AS WEARING PROTECTIVE CLOTHING WHEN WORKING WITH POTENTIALLY INFECTIOUS SUBSTANCES.







WARNING

THE INSTRUMENT COMPLIES WITH THE EMISSION AND IMMUNITY REQUIREMENTS DESCRIBED IN IEC 61326-2-6; HOWEVER, THE ELECTROMAGNETIC ENVIRONMENT SHOULD BE EVALUATED PRIOR TO THE OPERATION OF THE INSTRUMENT.

IT IS THE OPERATOR'S RESPONSIBILITY TO ENSURE THAT A COMPATIBLE ELECTROMAGNETIC ENVIRONMENT FOR THE INSTRUMENT IS MAINTAINED, SO THAT THE INSTRUMENT PERFORMS AS INTENDED.

DO NOT OPERATE THE INSTRUMENT IN CLOSE PROXIMITY TO SOURCES OF STRONG ELECTROMAGNETIC RADIATION (E.G. UNSHIELDED INTENTIONAL RF SOURCES) AS THIS MAY INTERFERE WITH THE PROPER FUNCTION OF THE INSTRUMENT AND MAY ALSO LEAD TO INCORRECT RESULTS.



General

2.1 Intended Use

The INFINITE F50 PLUS is an automated 96-well microplate absorbance reader including Magellan software for professional use in a laboratory for the measurement of light absorbance (optical density) of homogeneous liquid media for in vitro diagnostic use.

The instrument is intended to be used primarily in in-vitro diagnostic analysis of samples from the human body delivered from a user selected Enzyme-linked Assay (ELISA). The specific diagnostic information and type of specimen is defined by the selected assay.

The INFINITE F50 PLUS is intended for the measurement and the evaluation of qualitative, semi-quantitative, and quantitative assays according to scheduled diagnostic parameters and instrument specifications.

The product is intended for professional laboratory use by trained personnel. The product is not for home or lay person use.



Note

If the INFINITE F50 PLUS absorbance reader or the Magellan software is modified in any way, the warranty will no longer be valid, and the instrument will lose regulatory conformity.



Note

The operating authority must use only CE-labeled test kits for clinical diagnostic applications. The operating authority must assure that the combination of a particular CE-labeled test kit used with the CE-labeled INFINITE F50 PLUS absorbance reader and its options has been validated to meet the IVD regulation 2017/746, or other relevant national or local regulations.

If the INFINITE F50 PLUS absorbance reader is used differently from the 'Intended Use' mentioned above or if it is used with other software than Magellan, the instrument is no longer IVD conform, and the user is responsible for the respective use and the necessary validation.



Note

Results obtained using the INFINITE F50 PLUS are influenced by the proper use of the instrument and microplates, according to the instructions given in this document, as well as the liquid compounds used (reagents, chemistry). The instructions for use, storage, and applications involving samples or reagents must be followed strictly.

Results must therefore be interpreted carefully.



Note

Never open the housing of the instrument or the warranty will be rendered null and void.



2.2 Principle of Operation

The INFINITE F50 PLUS is an 8-channel absorbance reader for measuring the optical density (OD) of liquids in 96-well microplates.

The light created by the LED light source passes through an optical filter in the filter wheel for selecting the wavelength which is needed for the absorbance measurement.

After passing through the filter the light beam is split into eight optical fibers for focusing onto eight wells of the microplate. The light beams passing through the wells of the microplate, are being focused by eight optical lenses and are then sent to eight photodiodes for detection.

This means that the INFINITE F50 PLUS reader is measuring eight wells in parallel, which is corresponding to one column of a 96 well microplate.

For controlling and regulating the light intensity of the LED lamp, one additional optical fiber (reference channel) is used, where the light is bypassing the microplate.

The obtained transmission values are converted into optical density (OD) values according to the following formula:

Transmissi on
$$T = \frac{I}{I_0}$$

 I_0 = intensity of the incident light

I = intensity of the transmitted light

The OD is the logarithm of the reciprocal transmission.

$$OD = Log \frac{1}{T}$$



2.3 User Profile

2.3.1 Professional User - Administrator Level

The administrator is a person who has suitable technical training and corresponding skills and experiences. If the product is used as intended, the person is able to recognize and avoid dangers.

The administrator has extensive skills and is able to instruct the end user or the routine user in assay protocols in connection with a Tecan product within the bounds of the intended use.

Computer application skills and good English skills are required.

2.3.2 End User or Routine User

The end user or routine user is a person who has suitable technical training and corresponding skills and experiences. If the product is used as intended, the person is able to recognize and avoid dangers.

Computer application skills and good language skills for the respective national language at the installation site and English are required.

2.3.3 Service Technician

The service technician is a person who has suitable technical training and corresponding skills and experiences. If the product needs to be serviced or maintained, the person is able to recognize and avoid dangers.

Computer application skills and good English skills are required.



Note

Training dates, their duration and frequency are available at your customer support.

Address and phone number can be found on the Internet: http://www.tecan.com/customersupport



3. Getting Started

3.1 Unpacking and Inspection

3.1.1 Inspection of Delivered Packaging

The delivered instrument includes:

- External power supply
- Power cable
- · USB cable for connection to external computer
- Instructions for Use (IFU), PDF files on data-carrier
- USB stick
 - Software Magellan
 - Instructions for Use (IFU)
 - o Tools (e.g., Adobe Reader)



Note

To avoid undesired loss of data or virus/malware attack, never remove the write protection from the USB stick.



CAUTION

THE READER HAS BEEN TESTED WITH THE SUPPLIED USB CABLE. IF ANOTHER USB CABLE IS USED, THE CORRECT PERFORMANCE OF THE INSTRUMENT CANNOT BE GUARANTEED.

3.1.2 Unpacking Procedure

- 1. Visually inspect the packaging for damage before it is opened. *Report any damage immediately.*
- Select a location to place the instrument. The location should be flat, vibration free, away from direct sunlight, and free from dust, solvents, and acidic vapors. Ensure that the distance between the instrument and the wall or other equipment is at least 5 cm.
- 3. Lift the instrument out of the carton and place it in the selected location. Take care when lifting the instrument.
- 4. Visually inspect the instrument for loose, bent, or broken parts. *Report any damage immediately.*
- 5. Compare the instrument's serial number on the bottom plate of the instrument with the serial number on the packing slip.

 Report any discrepancy immediately.
- 6. Check the instrument accessories against the packing note.
- 7. Save packing materials for further transportation purposes.



3.2 Power Requirements

The instrument is auto-sensing for the supplied voltage. Therefore, it is not necessary to make any changes to the voltage range. Check the voltage specifications and ensure that the voltage supplied to the instrument is correct according to the following specifications:

Voltage:	
Basic instrument with AC adapter:	100 – 240 V AC, 50/60 Hz
Basic instrument without AC adapter:	24 V DC

If the above-mentioned voltage is not available in your country, please contact your local Tecan customer support.

Connect the instrument only to an electrical supply system with protective earth.



CAUTION

DO NOT USE THE INSTRUMENT IN AN INCORRECT VOLTAGE RANGE. IF THE INSTRUMENT IS SWITCHED ON WITH THE INCORRECT VOLTAGE IT WILL BE DAMAGED.



CAUTION

DO NOT REPLACE DETACHABLE MAIN POWER SUPPLY CORDS WITH INADEQUATELY RATED CORDS.

3.3 Environmental Requirements

The instrument should be placed on a flat, level surface that is free from dust, solvents, and acidic vapors.

Vibration and direct sunlight must be avoided to ensure correct results.

Ambient Temperature:		
Operation	15 °C to 35 °C (59 °F to 95 °F)	
Storage	-30 °C to 60 °C (-22 °F to 140 °F)	
Relative Humidity:	20 % to 80 % non-condensing at operation temperature	



3.4 System Requirements

	Supported	Recommended
PC	Windows compatible PC with a Pentium compatible processor running at 1 GHz (Dual Core)	2 GHz (Dual Core)
Operating System	Windows 10 (32-bit)	
	Windows 10 (64-bit) Editions: Pro	
Memory	Windows 10 (32-bit): 1 GB RAM	2 GB RAM
	Windows 10 (64-bit): 2 GB RAM	4 GB RAM
Free Hard Disk Space	3 GB	5 GB
Monitor	Super VGA Graphics	
Resolution	1024 x 600 and higher	1920 x 1080
Color Depth	256	
Mouse	Microsoft mouse or compatible pointing device	
Communication	1 x USB 2.0	2 x USB 2.0 1 x RS232 (Serial)
Devices	Windows 10: DirectX 9 graphics device with WDDM 1.0 or higher driver	
.NET	Microsoft .NET Framework 3.5: In Windows 10 the user will be prompted to install the required .NET framework (3.5) if it is not already present.	
Windows Installer	3.1 If this version is not present, the install/upgrade program will install it.	
Microsoft Excel	2007, 2010, 2013, 2016 (32-bit), 2019 (32-bit), Microsoft Excel 365 (32-bit) Only 32-bit editions supported! Starter editions NOT supported!	2010 (32-bit) 2019 (32-bit)



3.5 Switching ON the Instrument

The following procedures detail the necessary steps required before switching on the instrument.



CAUTION

BEFORE THE INSTRUMENT IS INSTALLED AND SWITCHED ON, IT SHOULD BE LEFT TO STAND FOR AT LEAST THREE HOURS, SO THERE IS NO POSSIBILITY OF CONDENSATION CAUSING A SHORT CIRCUIT.

When the requirements mentioned above have been met, installation is carried out using the following procedure:

- 1. Connect the instrument to the external computer with the USB cable.
- 2. Ensure that the main power switch on the left side of the instrument is in the OFF position.
- 3. Insert the power cable into the main power socket in the left panel.
- 4. Switch the instrument on using the main power switch in the left panel.

The instrument is ready to measure microplates upon software installation.



Note

Before starting measurements make sure that the microplate position A1 is inserted correctly.

Microplates can only be measured without lids.

Close the plate transport cover before starting a measurement to avoid ambient light influencing the results.



Note

Always unload the microplate from the reader directly after the measurement has been finished.



3.6 Software

3.6.1 Introduction / Intended Use

The instrument control and data analysis software **Magellan** is delivered with the instrument.

Magellan is a universal **reader control and data analysis software** for analyzing data generated by microplate tests using Tecan measuring devices.

Magellan is available in two versions:

- · Magellan and
- Magellan Tracker.

Magellan software is intended for endpoint, kinetic and multilabel assays with the INFINITE F50 PLUS instrument according to the intended use; see chapter 2.1 Intended Use.

Magellan Tracker offers all necessary functionality to become compliant with the FDA Regulation 21 CFR part 11 in addition to the functionality of Magellan.



Note

It is important to note that the proper installation of the instrument and the Magellan software alone will not ensure compliance with laws and requirements. Corresponding policies concerning processes and standard operating procedures, including validation and quality control, must also be established.

3.6.2 Installation Procedure

To install the software, insert the USB stick to the USB port and proceed as follows:

- 1. Magellan installation wizard should start automatically and guide you through the installation process. If it does not, please run the file 'E:\Tecan.exe' (where E is the drive letter of the USB stick).
- 2. Select 'Magellan software' and depending on the version you have ordered 'Install Magellan' or 'Install Magellan Tracker' to start the installation procedure and follow the wizard.
- 3. Click **Install** to start the software installation procedure.
- 4. Click I accept the terms of the license agreement and Next to continue.
- 5. The **Customer Information** page appears: please enter username and organization.
- 6. The **Configuration page** appears: choose the language.
- 7. Use for regulated environments page: click Next to continue.
- 8. Click Install to start the installation.
- 9. Click **Finish** to end the installation and to close the setup program.

The software can be started via the Windows **Start** menu by selecting **Magellan** in the program group **Tecan**.



Note

It is very important that the person who installs the software has administrator rights on the computer.





Note

Magellan V7.5 cannot be installed together with other versions of Magellan software.

By default, all file types associated with Magellan are stored in corresponding subdirectories in the following directory:

- Windows XP:
 C:\Documents and Settings\All Users\Documents\Tecan\Magellan
- Windows 7, Windows 8, Windows 10:
 C:\Users\Public\Documents\Tecan\Magellan

3.6.3 Installation Qualification

Check successful installation of Magellan with the automatic installation qualification program:

Start TecanIQ.exe from the default installation path (C:\Program Files\Tecan\Magellan) or from the Windows Start menu: Start > Programs > Tecan > MagellanIQ.

Click **Check** to start the installation qualification. All installed components should have status **OK**. Please contact your local Tecan sales representative if any potential problem is reported.

To close the installation qualification program, click Cancel or Exit.



Note

The installation qualification should be repeated each time Magellan is installed or updated to a newer version.



3.6.4 Start Working with Magellan


The main type of the user interface in Magellan is the wizard.

Standard Magellan wizards represent workflow modules, which are step-by-step guides for performing complex procedures.

Occasionally, menus are available in the heading bar. The **Menu** offers a conventional way of using the software: the relevant menu item is selected from the main menus. All subsequent actions are started instantly, or a dialog box is displayed where further selections or entries can be made.

User Interface – Wizard List

After launching Magellan, the Wizard List appears:



Each wizard can be started either by double-clicking or by selecting it and clicking the **Next** button.

Start Measurement Wizard

The **Start Measurement wizard** includes the following options:

- Obtain Raw Data is used to generate raw data quickly and easily by setting the required measurement parameters and starting a measurement.
- Use Predefined Method is used to perform measurements based on previously defined methods.
- **Start Favorite** is used to select one of the most frequently used methods from the list of numbered icons.

After the measurement is finished a workspace file is created.

Evaluate Results Wizard

The **Evaluate Results wizard** is used to view the raw data and to evaluate the results. The evaluation parameters can be viewed, and data can be re-evaluated.



Attach Signature Wizard

The **Attach Signature wizard** is used to sign method and workspace files. This feature is only available with Magellan Tracker.

Create/Edit a Sample ID List Wizard

The **Create/Edit a Sample ID list wizard** is used to create new and to edit existing sample ID lists.

Create/Edit a Method Wizard

The Create/Edit a method wizard is used to define or edit methods.



Note

For detailed information about the software please refer to the Magellan Instructions for Use.

Please note that some features described in the Magellan Instructions for Use might not be relevant (available) in the Magellan V7.5 version in combination with the INFINITE F50 PLUS. However, all necessary information is described in this IFU.



Note

Please find a detailed example of an ELISA measurement in chapter 6.


Sunrise method files created with Magellan V7.x or higher can be opened with Magellan V7.5; measurement parameters are converted automatically.

Sunrise methods created with earlier versions need to be converted using the 'Convert From' option in the miscellaneous/file handling menu.



3.7 Magellan - Measurement Parameter Editor

The **Measurement Parameter Editor** is used to set up workflows. Each workflow is easily created by dragging and dropping the process steps into a sequence according to the application. The application workflow is then visible to the user in the workflow pane. Each process step (program element) can be copied and pasted (using the Windows standard shortcuts **Ctrl-C**, **Ctrl-V** or context sensitive mouse menu) and moved to the desired position in the workflow.



The **Measurement Parameter Editor** consists of the following items which are described in detail in the subsequent chapters:

- Control Bar
- Workflow Pane
- Info Pane



3.7.1 Control Bar

The **Control bar** is divided into five sections. Each section contains program elements used to create an individual workflow.

Create a workflow either by double-clicking the selected program element or by dragging and dropping it into the workflow pane.


The following program elements are available when using an INFINITE F50 PLUS:

Lab Ware	Plate Part of Plate
Measurements	Absorbance
Actions	Shaking Move Plate
Kinetic	Kinetic Cycle Kinetic Condition
Miscellaneous	Comment User Request Wait (Timer) Incubation

Lab Ware


Plate

The **Plate** program element is used to select a plate format from the **Plate definition** drop-down list. Click **Details**... to see further information on the selected plate.



Part of Plate


By default, the **Part of Plate** program element is collapsed. When expanded by clicking it displays a 96-well microplate. To measure individual wells, click the desired well or to measure a range of wells drag a frame around the desired range. Clicking on **Details...**, the plate preview can be zoomed.





Independent Parts of Plate

Independent parts of the plate can be selected:



A second range of wells can be selected by pressing the **Control key** on the keyboard and dragging a frame over the wells to be selected.

Measurements

Absorbance

The **Absorbance** program element is used to perform absorbance measurements. Enter or select the respective parameters.


Two drop-down lists display the available measurement and reference filter wavelengths, according to the inserted absorbance filters. If the drop-down lists are empty, the filters have not been defined.



Actions

Shaking

Select the **Shaking** program element if the plate is to be shaken, either before the measurement or between kinetic cycles.



Enter the respective parameters:

Duration	Enter the duration of the shaking process.
Intensity	Enter the desired shaking mode. Amplitude and frequency are
	displayed when choosing the respective shaking mode.

See chapter 4.1.1 Microplate Shaking for available shaking modes.

Clicking the link <u>Wait a couple of seconds</u> inserts a new program element. See page 25 for details.



Kinetic

Kinetic Cycle

Use the program element **Kinetic Cycle** to perform several consecutive measurements, which may be executed in certain intervals.



Enter the respective parameters:

Cycles	Number of cycles: Enter a number or click the up or down arrows for the number of actual measurement steps (2 – 1000 cycles) Duration: Enter the duration, format hh:mm:ss.		
Kinetic Interval	Use kinetic interval : Enter the time interval (hh:mm:ss or ms).		

Kinetic Condition

Use the **Kinetic Condition** program element to define which actions should be executed at a certain cycle.



If **2** is entered for **Execute command at cycle** within a kinetic measurement containing, e.g., a **Shake** step, shaking is performed only at cycle 2.



Note


Kinetic conditions such as Shake should be inserted right after a Kinetic Cycle program element in order to ensure optimal result reproducibility. Users are advised to set up suitable scripts prior to the measurements and to use the same script for all similar kinetic measurements in order to obtain comparable results.



Miscellaneous


Comment

Use the program element **Comment** to enter a remark or statement for the current measurement in the text field.



User Request

The **User Request** program element informs the operator of the instrument to execute a definite action during the workflow at a certain time.



If for example the **Move Plate** program element is used to move the plate out to perform a certain action, then the entered text should inform the operator to perform these actions. A dialog box shows the message, and the measurement process stops until **OK** is clicked.

Wait (Timer)

Use the **Wait (Timer)** program element to define a certain waiting period before the next step within a workflow is executed.

In the Wait time field enter the required time.



Enter the respective parameters:

Timer	Enter the Wait time (hh:mm:ss)
Options	Ignore wait at last kinetic cycle: When the program step Wait (Timer) is the last action within a kinetic run, the wait time will be ignored in the last cycle.

Incubation



Enter the appropriate parameters for incubation:

Incubation time Enter the total time (min. 5 s)



3.7.2 Workflow Pane

The **Workflow pane** is the window, where the measurement script is visible and where parameters are defined and edited.

There are two ways to insert a program element from the **Control bar** into the **Workflow pane**:

- Select a program element from the Control bar; by double-clicking it, it is
 inserted into the Workflow pane directly after the previous program element.
- Click the program element in the **Control bar** and drag it into the **Workflow** pane to the respective position.

The program elements are numbered according to their sequence.

Once a program element has been inserted into the **Workflow pane**, settings and parameters for this element can be entered or edited.

Single program elements inside the **Workflow pane** can be collapsed to display the most important information or expanded to access all editable functions. Click one of the triangles next to the title of the program element, or b, to switch between the two view modes.

By default, the measurement parameter editor starts with the **Plate** element, the **Part of Plate** element (collapsed) and an **Absorbance** element in the **Workflow pane**.

Currently selected program elements within the **Workflow pane** are displayed with a yellow line on the upper border.

If a program element contains errors or is invalid within the current workflow, the element will be flagged with an error mark and the number of the element is highlighted in red. In the **Info pane** detailed information on the error is displayed. If the workflow contains errors, the measurement parameters cannot be chosen.

Hierarchy of Elements

The hierarchy of elements in the **Workflow pane** is as follows:

- 1. Plate
- 2. Part of Plate (Range)

Any desired measurement step can be inserted directly after a plate or range element. Use **Release** and **Indent** to modify the sequence of execution of the single strip component. Select an element in the **Workflow pane**, click the right mouse button and select **Release** or **Indent**.

Other elements from the **Control bar** can be inserted into the hierarchy of a workflow as follows:

The first **Range** element is inserted directly after the **Plate** element; then all subsequent **Range** elements can be inserted.

Kinetic steps are possible within a Plate or Range element.

User Request, **Comment** and **Wait** steps are possible within a **Plate** or **Range** element.

3.7.3 Info Pane

The **Info pane** on the right side of the screen displays information that is relevant for the currently selected program element. Any warnings and errors are shown.




3.8 Magellan - Defining Measurements

The following chapter describes some examples to illustrate the definition of different measurements.

3.8.1 Defining Endpoint Measurements

The following example describes an **Absorbance Endpoint Measurement** in all wells of a 96-well microplate.

- 1. Select a 96-well microplate from the **Plate definition** drop-down list.
- 2. By default, all wells of the 96-well microplate are chosen for measurement.
- 3. Enter the desired measurement and reference wavelengths.






3.8.2 Defining Multilabel Measurements

The following example describes an **Absorbance Multilabel Measurement** in a defined range of a 96-well microplate (A1:E7). Three absorbance labels shall be measured.

- 1. Select a 96-well microplate from the **Plate definition** drop-down list.
- 2. By default, all wells of the 96-well microplate are chosen for measurement. Click to expand the **Part of Plate** element. Thereafter, select the desired plate range (A1:E7).
- 3. Enter the desired measurement wavelength.
- 4. Insert 2 more **Absorbance** elements and enter the measurement wavelengths.






3.8.3 Defining Kinetic Measurements

The following example describes a kinetic measurement of a 96-well microplate.

- 1. Select a 96-well microplate from the **Plate definition** drop-down list.
- 2. Insert a **Kinetic Cycle** program element between the part of plate and the absorbance element.
- 3. Cycles/Number of cycles: 50
- 4. Kinetic interval (interval between measurements): select **Use kinetic interval** and enter: 2 minutes 30 seconds.
- 5. Define the **Absorbance** element by entering the desired measurement wavelength.





3.8.4 Indenting and Releasing Program Elements

The decision to indent/release a program element will modify the workflow of the instrument during measurements.


The actions of all program elements with the same indentation are performed sequentially. The only dependence between these program elements is that the next action starts directly after the previous action is finished.

A program element that is indented more than the previous program element shows dependence between the two program elements. This means the parameters defined in the first program element are also active for the second (indented) program element.

The following is an example of how to define a **Multilabel kinetic** with two **Absorbance labels**. The example shows that the two **Absorbance** program elements depend on the **Kinetic Cycle** program element, which depends on the **Part of Plate** program element, which depends on the **Plate** program element. Define the parameters for an example as follows:

- 1. Plate: e.g., Greiner 96 Flat Transparent
- 2. Kinetic Cycle/Number of cycles: 5
- 3. Absorbance/Wavelength Label 1: 450 nm
- 4. Absorbance/Wavelength Label 2: 492 nm

The Workflow pane appears as shown in the screenshot:




The definition above results in the following workflow:

The absorbance of all wells of the 96-well microplate is first measured at 450 nm and then at 492 nm. Both absorbance measurements are performed in 5 kinetic cycles.



Releasing the second **Absorbance** program element, so that it is aligned with the **Kinetic Cycle** element, changes the workflow. Select the second **Absorbance** program element and click the right mouse button. Select **Release Strip** from the context sensitive menu. The **Workflow pane** appears as shown in the following screenshot:



In this workflow, an **Absorbance kinetic** measurement with 5 cycles is done for the first absorbance at 450 nm; finished this loop, **Absorbance endpoint** measurement at 492 nm is performed.



3.9 Optimizing for Best Performance

The instrument has been fully factory tested to ensure that its performance is within the specified limits (see 4.4.2 Measurement Specifications for details).

The greatest accuracy can be obtained from the instrument by observing the recommendations mentioned below.

3.9.1 Instrument Location

The instrument should be positioned in an appropriate place (see chapter 3.3 Environmental Requirements for detailed information).

3.9.2 Operating Procedure

General

- It is recommended to follow the standard operating procedures for the assays used
- The best reproducibility is obtained, when the measurement wavelength corresponds to the maximum absorbance wavelength of the particular solution.
 - It is important to use the maximum absorbance wavelength, if the absorbance curve of the sample is over a narrow wavelength band.
 - Please be aware that measurements in the slope of an absorbance peak will limit the accuracy of OD values.
- After each microplate has been measured, please refer to the test kit package for information regarding the validation procedure.
- Use the recommended absorbance filters for the INFINITE F50 PLUS.

Microplates

- The instrument can be used with those types of microplates which are described in chapter 4.4.3 Microplates. The best results are obtained when flat bottom microplates are used. Depending on the type of microplate being used, the measurement results may vary.
 - Take care especially when using microplates with C-, U- or V-shaped bottom or strip-well plates because it is possible that the measurement results might differ to the specifications described in this document. Make sure that the type of microplate used with the INFINITE F50 PLUS absorbance reader is suitable for the respective application.
- Use only perfectly clean microplates.
- Do not allow dust to settle onto the solutions or the microplate during an incubation period prior to the measurement.
 It is recommended to use a cover for protection whenever a microplate is placed outside the instrument.
- Inaccuracies in the amount of solution pipetted have a greater effect on the results obtained, when small amounts of solutions are used.
- The form of the meniscus of the solution can cause inaccuracies in the results, particularly if small amounts of solution are used.



4. Instrument Features

4.1 Instrument Features

The following absorbance measurement modes are available on the INFINITE F50 PLUS:

endpoint, kinetic, and multilabel measurements.

4.1.1 Microplate Shaking

The INFINITE F50 PLUS can shake the microplate before it is measured. The microplate can also be shaken between each of the kinetic measurement cycles. Use Magellan to set the shaking mode.




CAUTION WHEN SHAKING MICROPLATES, SPILLAGE MAY OCCUR IF THE WELLS ARE FILLED WITH A TOO HIGH VOLUME.

Shaking modes for the INFINITE F50 PLUS:

Shake Mode	Shake Width	Shake Frequency
HIGH	2.8 mm	12.3 Hz
NORMAL	4.4 mm	9.2 Hz
LOW	4.4 mm	7.8 Hz
WIDE	14.1 mm	2.0 Hz

4.2 Instrument Description

The illustration below shows the components of the instrument.





The status LED gives information of the status of the instrument:

- Green blinking: instrument is not connected to Magellan
- Green: instrument is connected and ready for measurement
- Red: measurement is in progress

On the left panel of the instrument the USB port, main power switch, and main power socket can be found.



The nameplate is attached to the bottom of the instrument.

Example Name Plate



Contents of the name plate (e.g., model name and article number) may vary depending on the specific model.

For an overview of the various instruments for which these Instructions for Use are valid, see the Declaration of Conformity on the last page of this document.



4.3 Filter Wheel Description

The INFINITE F50 PLUS standard filter wheel is delivered with four narrow band interference filters that have a fixed wavelength (405, 450, 620, and 492 nm). It is possible to equip the filter wheel with up to 8 filters. For accessorily available filters please contact your local Tecan sales representative.

The filters of the standard filter wheel are mounted as listed below:

Filter position	Filter wavelength
1	405 nm
2	450 nm
3	620 nm
4	492 nm
5 - 8	empty filter positions



When a wavelength is selected for measurement the specific filter is brought into the light beam by moving the filter wheel to the according position.



Note
For more information about the definition of a new filter see
7.5.2 Defining Filters.



4.4 Instrument Specifications

The tables below list the specifications for the INFINITE F50 PLUS absorbance reader.

4.4.1 General Specifications

PARAMETERS	CHARACTERISTICS
Main power input External power supply	Power supply: Basic instrument with AC adapter: 100-240 V AC, 50/60 Hz, max. 1.2 A (auto sensing, Over voltage category II) Basic instrument without AC adapter: 24 V DC (Over voltage category I)
Consumption INFINITE F50 PLUS	Standby mode: approx. 12 VA Operational mode: max. 30 VA
Outside dimensions	Width: 34.7 cm(13.66 inch) Depth: 18.9 cm(7.44 inch) Height: 13.4 cm(5.28 inch)
Weight	2.6 kg (power supply included)
Ambient temperature:	
Operation	15 °C to 35 °C (59 °F to 95 °F)
Storage	-30 °C to 60 °C (-22 °F to 140 °F)
Relative humidity	20 % to 80 %
Pollution degree	2
Method of disposal	Contaminated waste
Environment	See chapter 3.3 Environmental Requirements for more information.



4.4.2 Measurement Specifications

PARAMETERS	CHARACTERISTICS	
Measurement time: single wavelength dual wavelength	< 15 seconds < 20 seconds	
Wavelength range: Standard	400 - 750 nm	
Measurement range: 400 - 750 nm	0 - 4.000 OD	
Resolution:	0.0001 OD	
Accuracy: 450, 492 nm 0.000 - 2.000 OD 2.000 - 3.000 OD	≤ (1.0 % + 0.010 OD)* ≤ (1.5 % + 0.010 OD)*	
Precision: 450, 492 nm 0.000 - 2.000 OD 2.000 - 3.000 OD	≤ (0.5 % + 0.005 OD)* ≤ (1.0 % + 0.005 OD)*	
Linearity: 450, 492 nm 0.000 - 2.000 OD 2.000 - 3.000 OD	≤ 1 % ≤ 1.5 %	
Wavelength selection: Standard filter	Narrow bandwidth interference filters. Up to 8 filters can be mounted in a filter wheel.	
Filter wavelength accuracy:	Central wavelength ± 2 nm	
Filter bandwidth: At 50 % transmission	10 ± 2 nm	
Light source:	LED	
Computer interface:	USB	
All connected devices must be approved and listed as per IEC 60950-1 Information Technology Equipment – Safety and equivalent local standards.		

^{*} better than or equal to x % of measurement value plus corresponding OD value.

4.4.3 Microplates

All 96-well microplates with transparent bottom (flat, C-, U-, and V-shaped; including strip-well microplates) that are conform to the following standards can be used with the INFINITE F50 PLUS absorbance reader:

ANSI/SBS 1-2004; ANSI/SBS 2-2004; ANSI/SBS 3-2004; ANSI/SBS 4-2004



CAUTION ONLY USE MICROPLATES WITHOUT LIDS AND DO NOT USE MICROPLATES HIGHER THAN 15.2 MM.


Handling the Microplate

Insert or remove the microplate only when the plate transport is fully ejected (as illustrated below) and the plate transport motor is not active. Do not open the housing lid when the Status LED lights up red.





WARNING ALWAYS WEAR DISPOSABLE GLOVES AND PROTECTIVE CLOTHING WHEN HANDLING THE MICROPLATE.



Position of well A1

Plate transport - fully ejected

4.5 Instrument Accessories

The list below contains the available optional accessories for the INFINITE F50 PLUS, which can be ordered additionally:

- Supplementary filters
- Filter assembly tool
- MultiCheckTM plate for INFINITE F50 family

For further information and availability in your country please contact your local Tecan sales representative.



5. Quality Control

5.1 Introduction



CAUTION

IF AT ANY TIME THE ANALYTICAL PERFORMANCE
OF THE INFINITE F50 PLUS IS IN QUESTION,
FOLLOW THE INSTRUCTIONS GIVEN FOR QUALITY CONTROL
OR CONTACT YOUR LOCAL TECAN CUSTOMER SUPPORT.

This chapter provides information about the self-check procedure for the instrument and instructions on how to easily check the operational quality.

5.2 Self-Check Procedure

During the connection of the INFINITE F50 PLUS to the Magellan reader control software, motors and sensors are checked and plate carrier and filter wheel are initialized.

Prior to each measurement a self-check calibration procedure is performed to ensure that the instrument is working correctly and to calibrate the optical system.

5.3 Operational Qualification (OQ)

The following tests can be performed to ensure that the instrument is working correctly, and accurate results are being obtained.

The reproducibility and accuracy of the instrument may vary with the type of solution and microplate used.

To eliminate this effect, the instruments are tested in the factory with a calibration plate, which removes the influence of the solution and any variation due to the positioning of the microplate when it is being measured.

5.3.1 MultiCheck Test

The MultiCheck test provides an automated check of reader performance including accuracy, linearity, precision, and alignment with NIST traceable standards.

5.3.2 Microplate Test

If the optical densities of the wells in the microplate are not consistent, the results obtained with this type of microplate will be influenced.

This inconsistency can be checked by reading an empty microplate.

The OD values obtained from the measurement of the empty microplate should be in a narrow range. For example: ± 0.010 OD.

If the OD values are not within this range this type of microplate should not be used.

By using dual wavelength measurements, the influence of the difference in OD values of the microplate is removed or reduced to a level that is within acceptable limits.



5.3.3 Instrument Precision with Liquid Samples

This procedure can be used to check the reproducibility of the measurements. The use of a microplate with flat bottom is recommended.

Fill a new microplate with a freshly prepared Orange G solution; use different dilutions of the solution in each well so that a range of optical densities is obtained. Make sure that the wells contain at least 200 μ l. The dilution series should be within the range of 0.1 to 3.0 OD. To reach about 3 OD it is recommended to use 125 mg.l⁻¹ Orange G (Sigma, Cat. No. O7252).

Define a test run using the 492 nm filter and then measure the microplate at least three times.

For each well calculate the:

- average OD value
- standard deviation

Example

Readings 0.000 to 2.000 OD

The standard deviation of each well should be within (0.5 % + 0.005 OD).

Calculation of maximum allowed deviation using 1.000 OD as average OD value:

1.000 * 0.5 % + 0.005 = 0.010 OD

Readings 2.001 to 3.000 OD

The standard deviation of each well should be within (1.0 % + 0.005 OD).

Calculation of maximum allowed deviation using 2.400 OD as average OD value:

2.400 * 1.0 % + 0.005 = 0.029 OD

Readings above 3.000 OD

Readings above 3.000 OD are only used as an indication and the precision cannot be guaranteed.

5.3.4 Instrument Linearity with Liquid Samples

The linearity for the instrument and application at the wavelength used can be checked by using a dilution series of a solution.

The result depends on the purity of the dye used and the meniscus of the liquid in the wells.

As a reference, a dilution series of Orange G solution for measurements at 492 nm can be used.

The dilution series should be within the range of 0.1 to 3.0 OD. To reach about 3 OD it is recommended to use 125 mg.l⁻¹ Orange G (Sigma, Cat. No. O7252).

For other wavelengths, different solutions must be used.

200 μ l of each dilution are then pipetted into the microplate, a minimum of at least two samples should be used for each dilution to reduce the errors caused by pipetting.

The microplate is then measured and a linear regression of OD against concentration is drawn from the average of the measured OD values.

Determine the unweighted residual square value R² of the regression line.

Typical residual square values for a standard application are equal or better than $R^2 = 0.998$.



Note

Data can vary due to pipetting inaccuracy.



6. Application Example

6.1 Introduction

The Magellan **example files** provide Magellan methods and workspaces to introduce the software and to ease the user's work with it. The example files for a quantitative and a qualitative ELISA assay are installed automatically upon installation of Magellan.

6.2 Step-by-Step Example: Quantitative ELISA

A step-by-step example (quantitative test) of how to create a method in Magellan is provided in this chapter. By following the instructions, you will learn how to define evaluations from a test kit description in Magellan.



A B C D E F G H

Note

Example files automatically appear in the Method List in Magellan.

For Magellan Tracker, these files are available in the default data path and must be converted.

6.2.1 Test Kit Description

In the manufacturer's test kit description of a quantitative IgM – Antibody detections – ELISA the following instructions are found: Plate Layout

1	2	3	4	5	6	7	8	9	10	11	12
BLK	C3	S1									
NC	C4	S2									
NC	C4	S2									
C1	C5	S3									
C1	C5	S3									
C2	C6										
C2	C6										
С3	S1										

BLK = Blank, NC = Negative control, C1 - C6 = Calibrators (Standards), S1 - S... = Samples



Measurement and Evaluation

Read plate at a wavelength of 492 nm, reference at 620 nm.

Blank reader/plate on well A1.

Concentrations of the Calibrators (Standards):

Calibrator 1	5 UA/ml
Calibrator 2	10 UA/ml
Calibrator 3	20 UA/ml
Calibrator 4	40 UA/ml
Calibrator 5	80 UA/ml
Calibrator 6	160 UA/ml

After the blank correction the optical densities (OD 492 - OD 620) are plotted versus the concentration. The regression line that goes through these points is the standard curve.

Interpretation of the test results:

IgM < 18 UA/mI	Negative
18 UA/mI ≤ IgM < 22 UA/mI	Intermediate
IgM ≥ 22 UA/mI	Positive

The calculated IgM concentration of both negative controls must be under 8 UA/ml.

Data Handling

After the measurement, the data file (workspace) is stored automatically and a report containing the measurement parameters, plate layout, blanked values, standard curve, IgM-concentrations, cutoff definition, qualitative results of the samples and validations is created.

Additionally, the layout and the qualitative results are being stored as ASCII file.




6.2.2 Create a Method

In the **Wizard List** dialog box, select **Create/edit a method** and click **OK**. Click **Continue** on the **Welcome** page of the **Create/edit a method wizard** and the **Select a file** dialog box appears. Select **New**.



Measurement Parameters

Click Make Your Selection and the Measurement parameters page appears:






On the **Wavelength** strip select 492 nm as Measurement wavelength and 620 nm as Reference wavelength.




Continue Wizard by clicking **Choose measurement parameters** and the **Plate layout** window is displayed.





Design Layout

Define the plate layout using the **Well Assignment** dialog box on the right side of the screen.



In the Identifiers group box, select BL (Blank).

In the **Experimental** group box the number **1** remains.

In the Replicates group box, All is selected automatically.

Click well A1, which is then marked with a red border.

Click **Fill selection** and the well is labeled with the selected identifier type.



Note A single well can also be filled by double-clicking it.

Now choose the following settings in the **Well Assignment** dialog box:

In the **Identifiers** group box, select **NC** (Negative Control).

In the **Experimental** group box, the number 1 remains.

All in the Replicates group box is selected automatically.

Starting at well **B1** click and drag the mouse to **C1**. The wells **B1** to **C1** are then marked with a red border.

Click **Fill selection** and the wells are labeled with the selected identifier type.

Calibrators (standards) must be assigned to wells **D1** to **G2**. Select the following settings in the **Well Assignment** dialog box:

In the Identifiers group box, select ST (Standard).

In the **Experimental** group box, the number 1 remains.

In the **Replicates** group box, choose between **Fix number** and **All**.

Fix number:

Only enabled for standards and samples where IDs can be used.

If this **Fix number** button is active a number can be entered in the corresponding text field. This number defines how many replicates are intended for this method. In the selected wells, the entered number of replicates for every ID is created. Therefore, the number of selected wells must be a multiple of the entered number of replicates.



AII:

All selected wells are defined as replicates. If an existing ID number for the samples and standards is chosen, the selected wells are then added as replicates to the existing replicates. With all other identifier types the selected wells are added as replicates to the existing replicates.

Two arrow buttons define the direction of the replicate and ID number sequence (horizontal or vertical).

In this example select Fix Number and 2.

In the **ID-Number** box and in the **Replicates** group box select the **vertical** arrows.

Then select the wells D1 to G2 and click **Fill selection**.



Note

Select the wells as follows: Starting at well D1 click and drag the mouse over the required wells to H1. Then hold down the control (Ctrl) key and drag the mouse over the required wells from A2 to G2.

The Plate Layout appears as follows:



Click **Select all unused** from the toolbar to select all empty wells on the plate. Then hold down the control (Ctrl) key and click the well **H12**, so that it remains blank and unmarked

In the Well Assignment dialog box select SM (Sample) under Identifiers.

In the Experimental group box, the number 1 remains.

In the Replicates group box choose Fix number and 2.


In the **ID-Number** box leave 1 and in the **Replicates** group box select the **vertical arrows**. Click then **Fill selection**. The layout definition procedure is complete.



Transformations

In the control bar on the left of the window select the next option, **Add new transformation...** from the **Transformed data** item, to define blank reduction.

A dialog box appears asking you if you want to define a blank reduction. Click **Yes**. The following window appears:



Difference Data is selected automatically in the **Input data** box. If you have confirmed the definition of a blank reduction before, the software automatically names it **Blank reduction** (see transformed data in the control bar).

In the **Formula** box automatically appears **x-BL1** for this blank reduction, where x refers to the current input data value in a well and BL1 is the mean value of the blank wells of experimental group 1.

For further details and explanations concerning the definition and assignment of transformations, refer to the Magellan Instructions for Use.

In each well the following information appears (example well A5):

SM1_9	Sample, experimental group number 1, sample ID number 9.
2/2	Number of replicates is 2, total number of replicates is 2.
x-BL1 or 1	Assigned transformation x-BL1 (when Transformation is selected) or Dilution Factor value of 1 (when Conc., Dil,. Refvalues is selected).



Concentration / Dilution / Reference Value Definition


In the control bar select **Conc.**, **Dil.**, **Ref.-value**s from the **Method layout** item to define the respective values as described in the test kit.

Calibrator 1	5 UA/ml
Calibrator 2	10 UA/ml
Calibrator 3	20 UA/ml
Calibrator 4	40 UA/ml
Calibrator 5	80 UA/ml
Calibrator 6	160 UA/ml

Make sure ST is selected in the Select Identifier list.

In the **Identifier** list, a list of the standards from the Exp. Group 1 appears. In the corresponding **Concentration** box of **ST1_1** type the number **5** and in the **Unit** box, type UA/ml. In the corresponding **Concentration** box of **ST1_2** type the number **10**. The unit only needs to be defined once and is valid for all standards. Type the values for the ST1_3 to ST1_6 in the same way.

The screen showing the plate layout and the concentration is displayed:






Standard Curve

In the control bar click **Standard curve** from the **Concentrations** item to define the appropriate standard curve.


The following is in the test kit description:

After the blank correction, the optical densities (OD 492 - OD 620) are plotted versus the concentration. The regression line that goes through these points is the standard curve.

On the Data tab, select Blank reduction as input data.




On the Analysis type tab, select Linear regression.






On the Axis tab, define the labeling and the scaling of the axis as shown below:



On the **Graph** tab, define the graph title, curves, font, and graph display.





Define Cutoffs

In the control bar select **Cutoff definition** from the **Evaluate data** item to define the limits for the qualitative evaluation.

The test kit description contains the following instructions:

Interpretation of the test results:

IgM < 18 UA/ml	Negative
18 UA/ml ≤ IgM < 22 UA/ml	Intermediate
IgM ≥ 22 UA/mI	Positive

Use the following procedure to define the appropriate cutoffs:


In the Input data box, select Mean conc. (UA/ml).

The **Cutoffs** table represents a scale indicating the high and the low end for the **Limits** and **Labels**. In **Limits**, type 22 as the first (higher) limit and 18 as the second (lower) limit.

In **Labels**, enter the test interpretation (**Positive**, **Intermediate** and **Negative**) into the individual boxes. Use the drop-down color palette to assign a color:

- Positive Red
- Intermediate Blue
- Negative Green

The screen contains the following:



Click **Cutoff results selection** to select the identifier types for which the cutoff results must be shown.



Define QC Validations

In the control bar, click **QC Validations** from the **Evaluate data** item. Validation criteria for the test must be defined, so that the validity of the test results is guaranteed.

In this example the following requirement must be fulfilled:

The calculated IgM-concentration of both negative controls must be under 8 UA/ml.

In the Input box, select Single conc. (UA/ml).

In the first row, type NC1_1<8




Note

NC1_1 means Negative control of experimental group 1, replicate 1.

In the second row, type NC1 2<8.


The **QC Validations** dialog box is now displayed as follows:





6.2.3 Organize Printed Report

In the control bar, click **Printed repor**t from the **Data handling** item. The following screen is displayed:




On the **Data selection** tab, all available report data is contained in the **Available data** box. Using the **Insert and Append** buttons, data can be transferred into the **Selected data** box. Data can also be transferred using drag-and-drop.

In the **Print as** box, choose between printing the data as a matrix or as a list with a special orientation.

In this example a report containing the measurement parameters, plate layout, blanked values, standard curve, IgM-concentrations, cutoff definition, qualitative results of the samples and validations should be created.


Before creating the report, the default **Vertical list/Difference data** must be removed from the **Selected data** box. Only **Measurement parameters** remain in the **Selected data** box. **Print as List** must be changed to **Print as Matrix**.





Select **Method layout/Layout** in the **Available data** box and attach it as a matrix to the report by clicking **Append**. Then insert **Blank reduction**, **Mean conc. (UA/ml)** and **Cutoff results** into the matrix by selecting the corresponding items and clicking **Insert**.


Append Graph: Standard curve, Cutoff definition, and QC Validation criteria to the selected data. The data setup part of the report definition procedure is complete; the **Printed Report** dialog box looks like this:



On the **Header** and **Footer** tabs, define the layout of the header and the footer of the report (see Magellan Instructions for Use for further details).

Data Export

In the control bar, select **Data export** from the **Data handling** item. In this example, the layout and cutoff results should be stored as ASCII file. Select **Layout** and **Cutoff** results from the **Available data** window; click the → arrow to insert them into the **Selected data** window. The screen displays the following information:








Note

Exported data should always contain the Layout or Sample ID List.

Automated Data Handling

In the control bar, select **Automated data handling** from the **Data handling** item.




Select **export to ASCII file**, and **view results after measurements**. In Magellan **Tracker, save workspace** is selected by default and cannot be modified.



Save the Method

Click **Next** to open the **Save as** window. Enter the method filename and complete any other field if appropriate.




Filename text field	A filename must be entered. A default filename is suggested automatically but can be changed.
File remarks text field	Comments entered here will be saved and displayed with the filename.
Audit trail comment text field	Comments entered here will be stored in the audit trail. This option is only available with Magellan Tracker .
Organize Favorites button	The Organize Favorites dialog box appears.
Method password text field	Enter a method password to protect the method.
Run this method now check box	The method will be run immediately after clicking Save&Finish.

For further details, please refer to the Magellan Instruction for Use.



6.2.4 Run the Method

If Run this method now is selected in the Save as dialog box of the Create/edit a method wizard, the Start Measurement Wizard/Start Measurement dialog box will appear after Save is clicked. In the Start Measurement dialog a default workspace name is assigned and can be altered by the user if desired.



Click **Start** to start the measurement. A workspace will be created automatically, which contains all previously entered information and will collect all measurement values. While the measurement is being executed, a measurement status dialog box appears indicating the progress of the measurement.

After the measurement is completed, the **Results** dialog box appears, in which all the results and calculations can be viewed. Error messages can occur when performing a measurement without the according liquids (e.g., standards).



6.2.5 Evaluate the Result


Select **Evaluate results** to view and evaluate raw data. The evaluation parameters can be viewed, and data can be re-evaluated.

This section guides you through the **Evaluate Results wizard** using an example workspace file automatically installed upon installation of Magellan.

In the Wizard List dialog box, click Evaluate results.

Click **Next** on the **Welcome** page of the **Evaluate Results wizard** and the **Select a file** dialog box appears.


Select the workspace **Quantitative ELISA example_Sunrise_InfiniteF50.wsp** from the file list and click **Make your selection**. Calculations are executed and the following plate layout window is displayed:




In each single well the calculated value is displayed. Depending on the selected item in the control bar, the plate layout window changes correspondingly. Parameters and settings can be changed using the items in the control bar. If the method is to be modified, click on the **Edit method** tab.



Click in the well with the right mouse key and the context-sensitive menu appears:



Selecting **Summary** the following window is displayed providing detailed information of the definition and the settings of the chosen well:



Click **Next** in the plate layout window and the **Save** as dialog box appears, where you can enter a file name and remarks. Click the small **Save** button on the left of the window to save the file; you can continue working on the method or workspace. Click the **Finish** button on the right side at the bottom of the screen to save the file and to close the wizard. The program goes back to the wizard list.



6.2.6 Summary of Definition of Quantitative ELISA in Magellan

1. Subtract Blank value

Definitions in Magellan

Click on **Add new transformation** in the control bar and a window appears, asking if you want to define a **Blank reduction**. Click **Yes** and the **Blank reduction** formula is assigned automatically to all wells.

2. Define Concentrations

Definitions in Magellan (Control bar – Method layout/ Conc.-, Dil.-, Ref.-values)

Selected identifier: ST

Unit: UA/ml

ST1_1	5	(ST1_1Standard 1 first experimental group)
ST1_2	10	(ST1_2Standard 2 first experimental group)
ST1_3	20	(ST1_3Standard 3 first experimental group)
ST1_4	40	(ST1_4Standard 4 first experimental group)
ST1_5	80	(ST1_5Standard 5 first experimental group)
ST1_6	160	(ST1_6Standard 6 first experimental group)

3. Define Standard Curve

Definitions in Magellan (Control bar – Concentrations/ Standard curve)

Input data blank reduction
Analysis type linear regression

X-axis linear Y-axis linear

4. Define Cutoffs

Definitions in Magellan (Control bar – Evaluate data/ Cutoff definition)

Input data: Mean conc. (UA/ml)

Limits: 22

18

Positive ≥ 22 > intermediate ≥ 18 > negative

Non-competitive test



5. QC Validation

Definitions in Magellan (Control bar – Evaluate data/QC validation):

Input data: Single conc. (UA/mI)

Validation condition 1 NC1_1<8

Validation condition 2 NC1_2<8

NC1_1.....Negative Control first replicate first experimental group NC1_2.....Negative Control second replicate first experimental group



7. Cleaning, Maintenance, and Disposal

7.1 Introduction

This chapter contains the following procedures:

- Clean the instrument
- · Disinfect the instrument
- · Maintain the instrument
- · Insert or replace filters in the filter wheel
- Disposal instructions



WARNING

BEFORE DOING ANY CLEANING OR MAINTENANCE REMOVE THE MICROPLATE.



WARNING

PRIOR TO CLEANING AND DISINFECTING DISCONNECT THE INSTRUMENT FROM THE EXTERNAL POWER SUPPLY.



CAUTION

DO NOT MOVE THE PLATE TRANSPORT MANUALLY UNLESS THE INSTRUMENT IS SWITCHED OFF.

7.2 Cleaning the Instrument



WARNING

THE CLEANING PROCEDURE SHOULD BE PERFORMED IN A WELL-VENTILATED ROOM BY AUTHORIZED TRAINED PERSONNEL WEARING DISPOSABLE GLOVES AND PROTECTIVE GLASSES AND CLOTHING.

Clean the housing of the device and the plate transport only with a dry or moist cloth. If very dirty, clean it with a cloth moistened with a maximum of 70 % ethanol or mild detergent, Microcide SQ, or Decon 90. Wipe dry with a paper towel cloth.

If any liquid is spilled on the instrument, it should be immediately removed to prevent liquid running into the optical system causing loss of performance or an error message.



7.3 Instrument Disinfection



WARNING

IF LIQUID SPILLED ON THE PLATE TRANSPORT IS POTENTIALLY INFECTIOUS IT SHOULD BE DISINFECTED ACCORDING TO THE RELEVANT NATIONAL LAWS AND REGULATIONS.

All parts of the instrument that came into contact with biological samples, patient samples, positive control samples, or hazardous material must be treated as potentially infectious areas.



WARNING

THE DISINFECTION PROCEDURE AND THE DISINFECTANTS SHOULD CONFORM TO THE RELEVANT NATIONAL LAWS AND REGULATIONS.



WARNING

IT IS VERY IMPORTANT THAT THE INSTRUMENT IS THOROUGHLY DISINFECTED BEFORE IT IS REMOVED FROM THE LABORATORY OR BEFORE ANY SERVICE IS PERFORMED ON IT.

Before the instrument is returned to the local sales representative or to a service center, all surfaces and the plate transport must be disinfected, and a safety certificate must be completed by the operating authority. If a safety certificate is not supplied, the instrument may not be accepted by the local sales representative or service center or custom authorities may hold it.

7.3.1 Disinfection Solutions

The outer surfaces and the plate transport of the instrument should be disinfected using a disinfectant such as:

- Microcide SQ
- Decon 90
- 70 % Ethanol



WARNING

RISK OF FIRE AND EXPLOSION!

ALCOHOLS, SUCH AS ETHANOL OR ISOPROPANOL, ARE FLAMMABLE AND WHEN IMPROPERLY HANDLED CAN LEAD TO EXPLOSIONS AND/OR FIRE. PROPER LABORATORY SAFETY PRECAUTIONS MUST BE OBSERVED.



CAUTION NEVER USE ACETONE AS IT WILL DAMAGE THE COVERS.



7.3.2 Disinfection Procedure

If the laboratory has no specific disinfection procedure, the following procedure should be used to disinfect the outer surfaces and the plate transport of the instrument.



WARNING

THE DISINFECTION PROCEDURE SHOULD BE PERFORMED IN A WELL-VENTILATED ROOM BY AUTHORIZED TRAINED PERSONNEL WEARING DISPOSABLE GLOVES AND PROTECTIVE GLASSES AND CLOTHING.



CAUTION


THE SURFACE DISINFECTANT CAN NEGATIVELY INFLUENCE THE PERFORMANCE OF YOUR INSTRUMENT, IF IT IS APPLIED OR ACCIDENTALLY GETS INSIDE THE INSTRUMENT.



WARNING

PRIOR TO DISINFECTION DISCONNECT THE INSTRUMENT FROM THE MAIN POWER SUPPLY TO AVOID ANY RISK OF FIRE OR EXPLOSION.

- 1. Wear protective gloves, protective glasses, and protective clothing.
- 2. Prepare a suitable container for all disposables used during the disinfection procedure.
- 3. Disconnect the instrument from the software and switch the instrument off.
- 4. Carefully move the plate transport out of the instrument.



- 5. Carefully apply the disinfectant solution on the plate transport according to the manufacturer's Instructions for Use.
 - Do not use too much disinfectant to prevent the solution flowing into the instrument or soiling the lenses when moving the plate transport into the device.
- 6. After the required contact time (according to the manufacturer's Instructions for Use) wipe the plate transport using a soft paper towel moistened with a mild detergent or distilled water to remove all traces of the disinfectant.



7. Carefully move the plate transport into the instrument.



- Carefully apply the disinfectant on the base plate of the plate transport.
- After the required contact time wipe the base plate of the plate transport using a soft paper towel moistened with a mild detergent or distilled water to remove all traces of the disinfectant
- 10.Carefully apply the disinfectant solution on all outer surfaces of the instrument.
- 11. After the required contact time wipe the instrument using a soft paper towel moistened with a mild detergent or distilled water to remove all traces of the disinfectant.
- 12. Wipe dry the outer surface of the instrument with a soft paper towel.
- 13. Repeat the disinfection procedure on any accessories which are being moved or returned.
- 14. Dispose of the container with the disposables according to the relevant national laws and regulations.
- 15. Disinfect your hands and clean them with a mild detergent.

When sending the instrument back to the local sales representative/service center please continue with the following steps:

- 16. Pack the instrument and its accessories.
- 17. Complete the safety certificate (see below) and attach it to the outside of the box so that it is clearly visible.

7.3.3 Safety Certificate

To ensure the safety and health of personnel, our customers are kindly asked to complete a **Safety Certificate** (which was delivered with the instrument) and attach one copy to the top of the container in which the instrument is returned (visible from the outside of the shipping container!) and another copy to the shipping documents before shipping it to the service center for service or repair.

The instrument must be disinfected at the operating authority's site before shipping (see 7.3.2 Disinfection Procedure).

The disinfection procedure must be performed in a well-ventilated room by authorized and trained personnel wearing disposable powder-free gloves, protective glasses, and protective clothing.

The disinfection procedure should be performed according to national, regional, and local regulations.

If a Safety Certificate is not supplied, the instrument may not be accepted by the servicing center.

Your local Tecan customer support can send you a new copy of the Safety Certificate, if required.



7.4 Preventive Maintenance Plan for INFINITE F50 PLUS

The following preventive maintenance procedures are recommended.

7.4.1 Monthly

Clean the housing and the plate transport with a mild detergent at least once per month; more often when necessary.



CAUTION NEVER USE ACETONE AS IT WILL DAMAGE THE COVERS.

7.4.2 Every 4 Years

It is recommended to replace the filters every 4 years.

7.5 Filter Replacement and Installation

The INFINITE F50 PLUS must be connected to Magellan in order to do a software guided filter insertion or replacement. If the connection is lost during the procedure, due to accidental interruption of the connection between the instrument to the computer, Magellan must be terminated, and the instrument has to be switched off. In this case, continue the procedure as stated below. When finished, reestablish the connection by restarting the device and Magellan and define the newly inserted filters.



CAUTION

WHEN HANDLING THE FILTERS, BE CAREFUL THAT THEY DO NOT BECOME SCRATCHED OR SOILED WITH FINGERPRINTS OR DUST.




7.5.1 Filter Switching Procedure

The filters of the standard filter wheel can be replaced or supplemented using the following procedure:

- 1. In the Wizard list window, click Miscellaneous.
- 2. Click Instrument control
- 3. Click Define filter slides...
- 4. Click Filter switching to start the procedure.
- 5. Remove any microplate from the plate transport!
- 6. Tilt the instrument carefully backwards until it lies on the back side with the bottom facing towards you.
- 7. Remove the cover plate from the bottom of the instrument by removing the orange screws.



8. Remove the magnetically fixed filter wheel by carefully pulling it out of the instrument.



9. Place the filter wheel on a clean flat surface.



10. When replacing a filter, use the filter assembly tool to remove the filter from the filter slot.

Please contact your local Tecan sales representative for the filter assembly tool and available filters.



- 11. Align the filter assembly tool with the notch of the stop-ring. Turn the tool and remove the stop-ring by pulling it out of the filter slot.
- 12. Turn the filter wheel over so that the filter slides out of the slot. Do not use the filter assembly tool to push filters out of the filter slot, as the filter could get scratched.
- 13.A new filter must be inserted into the filter slot in the correct direction taking care not to scratch the filter or get fingerprints on it.






Note
Make sure that the filter is inserted correctly.



14. Place the stop-ring on the end of the filter assembly tool and turn it so it cannot slip off.



- 15. Using the filter assembly tool, push the stop-ring into the filter slot and press firmly into place.
- 16. Rotate the tool until the notch in the stop-ring is aligned with the end of the filter assembly tool and remove the tool.



- 17. Place the filter wheel back into the filter wheel slot and push it deeper until it is secured magnetically.
- 18. Reattach the cover plate back onto the bottom of the instrument with the three orange screws.
- 19. Bring the device back into an upward position.
- 20. Click **OK** to finalize the procedure and initialize the filter wheel.
- 21. Define the newly inserted filter (see next chapter for detailed procedure).



7.5.2 Defining Filters

In the **Filter Definition** dialog box assign appropriate wavelengths to replaced filters by entering the new wavelengths in the corresponding positions.

If a filter has been inserted into a new filter position, activate the appropriate filter position by selecting the check box and entering the appropriate wavelength.

By clicking **Save**, the filter definitions will be saved, and the filters will be initialized.

Once the filters have been initialized, the instrument is ready for measurements.



Note

Be careful not to mix up the filter positions and filter wavelengths as this will lead to wrong measurement data.

7.6 Disposal

7.6.1 Introduction

Follow laboratory procedures for biohazardous waste disposal according to national and local regulations.

This chapter provides instructions on how to lawfully dispose of waste material accumulating in connection with the INFINITE F50 PLUS.



CAUTION

OBSERVE ALL FEDERAL, STATE, AND LOCAL ENVIRONMENTAL REGULATIONS.

7.6.2 Disposal of Packing Material

The packing material consists of recyclable material. If you do not intend to keep it for future use, e.g., for transport and storage purposes, please dispose of the packing material according to local regulations.

7.6.3 Disposal of Operating Material



WARNING

BIOLOGICAL HAZARDS CAN BE ASSOCIATED WITH THE WASTE MATERIAL (MICROPLATE) OF THE PROCESS RUN ON THE INFINITE F50 PLUS ABSORBANCE READER.

TREAT THE USED MICROPLATE, OTHER DISPOSABLES, AND ALL SUBSTANCES USED IN ACCORDANCE WITH GOOD LABORATORY PRACTICE GUIDELINES.

INQUIRE ABOUT APPROPRIATE COLLECTING POINTS AND APPROVED METHODS OF DISPOSAL IN YOUR COUNTRY, STATE, OR REGION.



7.6.4 Disposal of the Instrument

If you have any questions concerning the disposal of the device, please contact your local Tecan customer support.

Pollution degree	2 (IEC/EN 61010-1)
Method of disposal	Contaminated waste

ATTENTION

DIRECTIVE 2012/19/EU ON WASTE ELECTRICAL AND ELECTRONIC EQUIPMENT (WEEE)

NEGATIVE ENVIRONMENTAL IMPACTS ASSOCIATED WITH THE TREATMENT OF WASTE.

- DO NOT TREAT ELECTRICAL AND ELECTRONIC EQUIPMENT AS UNSORTED MUNICIPAL WASTE.
- COLLECT WASTE ELECTRICAL AND ELECTRONIC EQUIPMENT SEPARATELY.

WARNING

DEPENDING ON THE APPLICATIONS, PARTS OF THE INFINITE F50 PLUS MAY HAVE BEEN IN CONTACT WITH BIO-HAZARDOUS MATERIAL.

- MAKE SURE TO TREAT THIS MATERIAL ACCORDING TO THE APPLICABLE SAFETY STANDARDS AND REGULATIONS.
- DECONTAMINATE ALL PARTS BEFORE DISPOSAL.

For more information about the product, please contact:

Tecan Austria GmbH

Untersbergstrasse 1A

A-5082 Grödig/Salzburg

AUSTRIA/EUROPE

T+43 6246 8933 444

F +43 6246 8933 6444

E-mail: expertline-at@tecan.com

www.tecan.com







8. Troubleshooting

8.1 Introduction

The internal microprocessor controls and checks electronic functions as well as measurements, operations, and results. If the microprocessor detects a fault or an incorrect operating procedure, an error message is displayed on the computer.

8.1.1 Table of Error Messages and Troubleshooting

The following table gives a brief description of the error messages and the troubleshooting actions.



Note

If other error messages appear that are not mentioned in the table below please contact your local Tecan customer support representative.

Error Message	Description	Troubleshooting
System Error		
"Lid Open Error"	Lid open at start of a measurement	Close lid and start measurement again
"MTP Init Error"	MTP transport could not be initialized	Hardware problem: Electronic defect, belt broken or MTP transport mechanically blocked
"MTP lost steps abs(steploss) > max_steploss"	MTP lost steps during measurement Steploss: number of lost steps max_steploss: number of allowed steploss	Hardware problem: Electronic defect, rough-running mechanic
"Filter lost steps abs(steploss) > max_steploss"	Filter wheel lost steps during measurement. Steploss: number of lost steps max_steploss: number of allowed steploss	Hardware problem: Electronic defective, rough-running mechanic
"USB timeout"	Timeout in USB communication	System Error – report to customer support
"Lamp Low! Minimum: <i>minimum</i> , Maximum: <i>maximum</i> " This message appears with firmware versions up to V1.11.	Measured light intensity did not reach the expected range between <i>minimum</i> and <i>maximum</i>	Hardware problem: Electronic defect, broken fiber
From firmware versions V1.12 and higher the "Lamp Low" message is replaced by: "Prepare REF check"	Measured light intensity did not reach the expected range between <i>minimum</i> and <i>maximum</i>	Hardware problem: Electronic defect, broken fiber
"Wavelength Not Available! Wavelength: <i>wavelength</i> nm"	The filter with the wavelength wavelength could not be found in filter wheel	System error – report to customer support



8. Troubleshooting

Error Message	Description	Troubleshooting
System Error		
"Channel Low! Channel: channel_nr, Minimum: minimum, Maximum maximum	Signal on channel channel_nr did not reach the expected area between minimum and maximum	Hardware problem: Electronic defect, broken fiber
"Invalid Wavelength! Wavelength: wavelengthnm"	Filter wavelength is outside the range of wavelengths of the white and the blue LED	System error – report to customer support
"Lamp Overflow!" Minimum: minimum, Maximum: maximum.	Signal on ADC exceeds the expected area between minimum and maximum	Hardware problem: Electronic defect
"Value Not Set: value -1"	The value value is not set	System error – report to customer support
"Filter Init Error"	Filter transport could not be initialized	Hardware problem: Electronic defect, filter wheel transport mechanically blocked

8.1.2 Definition of 'Overflow'

If the result of the absorbance measurement is not within the instrument specifications (> 4.0 OD) an overflow will occur and the measured OD value of the respective well will be replaced by 'Overflow'. This is done by the controlling software and not by the instrument itself.

8.1.3 Power Failure

In case of power failure the following happens:

Power failure of the instrument, but not of the controlling computer (e.g. computer connected to uninterruptible power supply system): USB connection between instrument and computer will be lost. Error message by the controlling software is created.

Power failure of both instrument and controlling computer: the computer has to reboot. No measurement data will be available.



9. Abbreviations, Trademarks, and Symbols

9.1 Abbreviations

The following abbreviations are provided as a reference and may appear in the Instruction for Use.

Α	Ampere		
AC	Alternating Current		
ADC	Analog Digital Converter		
ANSI/SBS	American National Standards Institute/Society for Biomolecular Screening		
ASCII	American Standard Code for Information Interchange		
ASTM	American Society for Testing and Material		
°C	Degrees Celsius		
CE	CE conformity marking		
CFR	Code of Federal Regulations		
cm	Centimeter		
DC	Direct Current		
EC	European Community		
ELISA	Enzyme-linked Immunosorbent Assay		
EN	European Norm		
°F	Degrees Fahrenheit		
FDA	Food and Drug Administration		
Hz	Hertz		
IEC	International Electrotechnical Commission		
ID	Identification		
IFU	Instructions for Use		
IQ	Installation Qualification		
IVD	In vitro diagnostics		
IVDR	In Vitro Diagnostic Regulation (IVDR) (EU) 2017/746		
kg	Kilogram		
I	Liter		
LED	Light Emitting Diode		
LIS	Laboratory Information System		
mg	Milligram		
ml	Milliliter		
mm	Millimeter		
MTP	Microplate		
μl	Microliter		
NFM	Nonferrous Metal		
NIST	National Institute of Standards and Technology		

9. Abbreviations, Trademarks, and Symbols

nm	Nanometer		
NRTL	Nationally Recognized Testing Laboratory		
OD	Optical Density		
OQ	Operational Qualification		
PCB	Printed Circuit Board		
RF	Radio Frequency		
RoHS	Restriction of the Use of Certain Hazardous Substances		
SOP	Standard Operating Procedure		
USB	Universal Serial Bus		
UA	Arbitrary Units		
ΤÜV	Technischer Überwachungsverein (Technical Inspection Agency)		
V	Volt		
VA	Volt Ampere		
WEEE	Waste electrical and electronic equipment		

9.2 Trademarks

The following product names and any registered and unregistered trademarks mentioned in this document are used for identification purposes only and remain the exclusive property of their respective owners:

- MagellanTM, Infinite[®], MultiCheckTM, Tecan[®] and the Tecan Logo are trademarks of Tecan Group Ltd., Männedorf, Switzerland
- Windows[®] and Excel[®] are registered trademarks of Microsoft Corporation, Redmond, WA, USA
- Pentium[®] and AtomTM are trademarks of Intel Corporation, Santa Clara, CA, USA
- Adobe[®] Reader[®] is a registered trademark of Adobe Systems Incorporated, Seattle, WA, USA
- Microcide SQTM is a trademark of Global Biotechnologies Inc., Portland, ME, USA
- Decon 90TM is a trademark of Decon Laboratories Ltd., Hove, East Sussex, UK



9.3 Symbols

The following symbols appear on the instrument.

_	
	Manufacturer
	Date of manufacture
(€	CE conformity marking
UK	United Kingdom Conformity Assessed marking shows that the labeled product is following the applicable regulation in Great Britain.
[]i	Consult instructions for use
IVD	In vitro diagnostic medical device
UDI	Unique Device Identification The UDI symbol identifies the data carrier on the label.
REF	Catalogue number
SN	Serial Number
•	USB label
	WEEE symbol
50	China RoHS symbol
SUD OF SURFIC US	NRTL TÜV SÜD MARK
	Biological risks

Kinetic Measurements......29



Index

A		
Abbreviations75	L	
Absorbance23	Lab Ware Control Bar	22
Actions Control Bar23	Lab Ware Control Barring	
Application Example41	M	
Quantitative ELISA41		47
	Magellan	
C	Maintenance	
Cleaning63	Maintenance Plan	
Comment25	Measurement Parameter Editor	
Control Bar22	Measurements Control Bar	
Actions	Microplates	
Kinetic	Optimizing Performance	
Lab Ware	Miscellaneous Control Bar	
Measurements	Multilabel Measurements	28
Miscellaneous25	0	
n.	Operational Qualification	39
U	Linearity Test	
Defining Filters71	Microplate Test	
Defining Measurements27	MultiCheck Test	
Disinfection 63, 64	Precision Test	
Procedure	Optimizing Performance	
Safety Certificate66	Overflow	
Solutions64		
Disposal 63, 71	Р	
Instrument72	•	00
Operating Material71	Part of Plate	
Packing Material71	Performance Optimization	
	Plate	
E	Power Failure	
End Point Measurements27	Power Requirements	14
Environmental Requirements14	Program Elements	
Error Messages73	Absorbance	
Life wessages	Comment	
E	Incubation	
	Indenting and Releasing	
Filter Replacement	Kinetic Condition	
Filter Switching	Kinetic Cycle	
Filter Wheel35	Part of Plate	
	Plate	
	Shaking	
Incubation25	User Request	
Info Pane26	Wait (Timer)	25
Instrument		
Accessories	Q	
Description33	Quality Control	39
Features	•	
Location32	S	
Specifications		7
Operation in the second	Safety	
K	Safety Certificate	
	Self-Check Procedure	
Kinetic Condition	Shaking	
Kinetic Control Bar24	Software	
Kinetic Cycle24	Installation	17



Index

Installation Qualification	18
Magellan	17
Magellan Tracker	17
User Interface	19
Wizard List	19
Specifications	36
Switching ON the Instrument	16
Symbols	77
System Requirements	15
т	
Troubleshooting	73
U	
Unpacking Unpacking and Inspection	13

Unpacking Procedure	13
User Profile	11
User Request	25
W	
Wait (Timer)	25
Wizard	
Attach Signature	20
Create/Edit a Method	20
Create/Edit a Sample ID List	20
Evaluate Results	19
Start Measurement	19
Wizard List	19
Wizard List	
Workflow Pane	26



Tecan Customer Support

If you have any questions or need technical support for your Tecan product, contact your local Tecan Customer Support organization. Go to http://www.tecan.com/ for contact information.

Prior to contacting Tecan for product support, prepare the following information for the best possible technical support (see name plate):

- Model name of your product
- · Serial number (SN) of your product
- Software and software version (if applicable)
- Description of the problem and contact person
- Date and time when the problem occurred
- Steps that you have already taken to correct the problem
- Your contact information (phone number, fax number, e-mail address, etc.)



Declaration of Conformity

EU DECLARATION OF CONFORMITY

This declaration of conformity is issued under the sole responsibility of the manufacturer:

TECAN AUSTRIA GMBH, Untersbergstr. 1A, A-5082 Grödig, Austria

for the product:

Infinite F50

Part No.(or Cat. No.) Model Configuration
30183570 INFINITE F50 PLUS ---

GMDN or CND: 57862 Microplate reader IVD, automated

Basic UDI-DI: 764013748IVS10080000AEC

Intended purpose:

The INFINITE F50 Plus is an automated 96-well microplate absorbance reader including Magellan software for professional use in a laboratory for the measurement of light absorbance (optical density) of homogeneous liquid media for in vitro diagnostic use.

The instrument is intended to be used primarily in in-vitro diagnostic analysis of samples from the human body delivered from an user selected Enzyme-linked Assay (ELISA). The specific diagnostic information and type of specimen is defined by the selected assay.

The Infinite F50 Plus is intended for the measurement and the evaluation of qualitative semiquantitative, and quantitative Assays according to scheduled diagnostic parameters and instrument specifications.

The product is intended for professional laboratory use by trained personnel. The product is not for home or lay person use.

is in conformity with the provisions of the following European Directive(s) / Regulation when installed in accordance with the installation instructions contained in the product documentation:

Regulation 2017/746 - IVD-R

on in vitro diagnostic devices

Classification: Class A according Rule 5 (b)

Conformity assessment procedure: Self Declaration

Directive 2006/42/EC

on machinery

Directive 2011/65/EU

on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2) including Commission Delegated Directive (EU) 2015/863 (RoHS3) amending Annex II to Directive 2011/65/EU)

and that the standards referenced below were taken in consideration:

EN 61010-2-101: 2017

Safety requirements for electrical equipment for measurement, control and laboratory use – Part 2-101: Particular requirements for in vitro diagnostic (IVD) medical equipment.

EN 61326-2-6: 2013

Electrical equipment for measurement, control and laboratory use - EMC requirements - Part 2-6: Particular requirements - In vitro diagnostic (IVD) medical equipment

EN 62304: 2006+A1:2015

Medical Device software - Software life cycle processes

EN 62366-1: 2015

Medical Device software – Application of usability engineering to medical devices

EN ISO 15223-1: 2016

Medical devices. Symbols to be used with medical device labels, labelling and information to be supplied. General requirements

EN ISO 18113-3: 2011

In vitro diagnostic medical devices -- Information supplied by the manufacturer (labelling) — Part 3: In vitro diagnostic instruments for professional use

EN ISO 14971: 2019

Medical devices - Application of risk management to medical devices

EN ISO 12100: 2010

Safety of machinery - General principles for design - Risk assessment and risk reduction

EN IEC 63000: 2018

Technical documentation for the assessment of electrical and electronic products with respect to the restriction of hazardous substances

Tecan Austria maintains a quality system certified to the following standards:

EN ISO 9001: 2015

Quality management systems - Requirements

EN ISO 13485: 2016

Medical devices – quality Management Systems – Requirements for regulatory purposes